# PRECAUTION IN DESIGNING CRYSTAL DEVICE

## **Design Notice for Crystal**

### Vibration

Mechanical vibration of a piezo buzzer could cause frequency and amplitude change to the output frequency. Although the affect might be minimal, Epson recommends the following product mounting quidelines.

### ■ Mounting guideline

- (1) Ideally, the mechanical buzzer source should be mounted on a separate PCB from the crystal device.
- (2) It is advisable to use cushion or cutting PCB, if you mount on same PCB.
- (3) Traveling mechanical vibration is different just PCB or inside body. Last of all, it is advisable to confirm to inside body characteristics.

### PLL Oscillator (SG-8002 and HG-8002 Series)

### **■ PLL-PLL connection**

The 8002 series uses PLL technology. There are some cases where jitter will increase when connected to other PLL type devices. For application assistance, please contact Epson.


### ■ Design notice for SG-8002 and HG-8002 series.


- (1) The following initialization is required when VDD is supplied in a condition that OE terminal is "L", no concern when "OE" = "H" or "Open". (For example: Wired -OR connection.)
- (2) Item

All "P" version of SG-8002 and HG-8002 series. (i.e. PT, PH, PC)

(3) Initialization

Initialization will be completed by adding a pulse stated below. It shows the case of wired-OR with 2 parts.





### Jitter Specifications

	Model	Operating Voltage	Jitter Item	Specifications	Remarks
	PT/PH ST/SH	5V±0.5V	Cycle to cycle	150ps max.	33MHz≤fo≤125MHz,C∟=15pF
				200ps max.	1.0MHz≤fo<33MHz,C∟=15pF
			Peak to peak	200ps max.	33MHz≤fo≤125MHz,CL=15pF
				250ps max.	1.0MHz≤fo<33MHz,CL=15pF
	SC/PC	3.3V±5%	Cycle to cycle	200ps max.	1.0MHz≤fo≤125MHz,C∟=15pF
			Peak to peak	250ps max.	1.0MHz≤fo≤125MHz,C∟=15pF